



Case Study Roofing

Client | Knightsbridge Property Services Role | Specialist Sub-Contractor

Before: Failed Mineral Felt Waterproofing





After: Cold, Liquid-Applied Application

The scope of this refurbishment was re-waterproof the roof of this school which had historic leaks and issues with outgassing blisters.

The existing mineral felt waterproofing was badly damaged with numerous cracks running throughout it, showing it had come to the end of it's serviceable life and allowing water ingress into the structure below. Countless patch repairs were previously completed to the original waterproofing system all of which had failed once again allowing water

Before: Numerous Cracks in the Mineral Felt





After: 100% Seamless

ingress.

Following localised repairs to the outgassing blisters, Westwood's Wecryl 230 fully reinforced waterproofing system was applied to 900m², overlaying the existing mineral felt system. The new liquid-applied seamless system encapsulated the cracks resolving the water ingress and leaving the structure watertight.

Due to the time of year this project took place, we had a challenge with the temperatures being too low and rain-fall.

Before: Failed Patch Repairs





After: Watertight Overlay of School Roof

Taking this into account, works were phased according to the weather and the waterproofing system was chosen due to it's ability to cure even during lower temperatures.

Included in our package of works was the removal and replacement of the edge trim detail. All our operatives were harnessed into a man-safe fall-arrest system for safe working at height.

For further advice and/or information regarding ALL of our services, please visit www.cemplas.co.uk.



Cemplas Waterproofing & Concrete Repairs Ltd

Cemplas House, 25A, Breakfield, Ullswater Industrial Estate, Coulsdon CR5 2HS **T:** 020 8654 3149 **E:** info@cemplas.co.uk **W:** www.cemplas.co.uk