

Case Study Concrete Repair & Protection

Client | BAM Construction Role | Specialist Sub-contractor Consultant | Fielden Clegg Bradley Studios

Architectural Concrete Refurbishment

South Bank Centre, London

SCOPE

I Concrete Repairs*I* Re-rendering

DETAILS

 Extensive concrete restoration and repair works to internal architectural concrete elements

 Queen Elizabeth Hall, Hayward Gallery & Purcell Room restored
Renovated board-finished concrete walls and coffered

concrete ceilings

Case Study // Client | Role Concrete Repair & Protection // Consultant | Fielden Clegg Bradley Studios

BAM Construction Specialist Sub-contractor

As part of a two-year, £28 million restoration of London's prestigious South Bank Centre, Cemplas have completed extensive concrete restoration and repair works to the internal architectural concrete elements of this globally famous arts venue.

Queen Elizabeth Hall, Hayward Gallery & Purcell Room have been restored to their original character including renovating board-finished concrete walls and coffered concrete ceilings. Remmers' Arte Mundit 'peelable' poultice was applied which, when peeled away, removed superficial dirt that had built up on the concrete. The rear walls of the Queen Elizabeth Hall stage also saw black paint removed using the 'Doff' method and Tensid Tavec 201 Biodegradable paint remover. Once cleaned, repairs have had to be carried out and blended in to ensure that they are not easily visible.

To view the previous case studies of specialist works undertaken by Cemplas, please visit www.cemplas.co.uk



Remmers' Arte Mundit 'Peelable' Poultice





Cemplas Waterproofing

& Concrete Repairs Ltd Cemplas House, 25a, Breakfield, Ullswater Industrial Estate. Coulsdon CR5 2HS

- T: 020 8654 3149 F: 020 8656 6984
- E: info@cemplas.co.uk W: www.cemplas.co.uk





Before: Repair Works



Constructionline

7NFRC

Cleaned Surfaces

H UVDB





Acclaim smas



www.cemplas.co.uk