

'Comfortfloor' Application

Fat Face Clothing, Havant

SCOPE

- // Concrete Repairs
- // Waterproofing

DETAILS

- // Installation of Sikafloor solutions to Staff Picking Area and Access Staircases and Landings
- // Application of Sikafloor Level 30 to approximately 70 stair treads
- // 300m² main Staff Picking Area
- // Comfortfloor applied to improve floor's comfort underfoot

Case Study // Flooring


Client | **BAM Construction**
 Role | **Specialist Sub-contractor**



Staff Picking Area



Landings



Access Stairwells

Cemplas has installed Sikafloor solutions to the Staff Picking Area and Access Staircases and Landings within this warehouse facility in Hampshire.

The works within the two access stairwells comprised the application of Sikafloor Level 30 to approximately 70 stair treads providing a suitably level surface for the application of Sikafloor 264 self-smoothing epoxy resin to staircases and 12 landing areas. Within the main Staff Picking Area, following preparation of the concrete floor, Sikafloor Level 30 was applied followed by 161 Primer and the application of

Sikafloor 327 Comfortfloor to an area measuring approximately 300m². The floor was finished overall with a coat of Sikafloor 305W matt finish. Comfortfloor was applied to improve the floor's comfort underfoot for staff pickers and provide a seamless floor finish.

To view the previous case studies of specialist works undertaken by Cemplas, please visit www.cemplas.co.uk



Cemplas Waterproofing & Concrete Repairs Ltd
 Cemplas House, 25a, Breakfield, Ullswater Industrial Estate, Coulsdon CR5 2HS

T: 020 8654 3149 F: 020 8656 6984
 E: info@cemplas.co.uk W: www.cemplas.co.uk

