

Concourse Resin Flooring


Crystal Palace Football Club, Selhurst Park Stadium

SCOPE

- // Concrete Repair
- // Resin flooring

DETAILS


- // Mechanically prepare concrete substrate
- // 50m² of concrete repairs to the substrate
- // Application of BASF Mastertop 1324 System to 1100m²



Case Study // Stadia

Client | Crystal Palace Football Club
Role | Principal Contractor

Before: Dark & Unwelcoming Environment



After: Repaired & Protected

Cemplas were invited by Crystal Palace Football Club to view the Arthur Wait Stand Concourse and undertake the application of sample areas of BASF Mastertop 1324 Resin flooring system.

Following a competitive tender process Cemplas were appointed as Principal Contractor to carry out the flooring works with the system selected meeting aesthetic, durability and slip resistance requirements. Externely tight timescales

Before: Substrate Damage



After: Enhanced Environment

were a factor given that the works needed to be completed for the first home game of the season.

The concrete substrate was mechanically prepared to including some substrate removal to an external area. Approx some 50m² of the concrete substrate had to be repaired prior to the application of the Mastertop 1324 system that the client had chosen to match with the clubs colours.

Before: Unprotected Concrete



After: Light & Bright Interior Improvements

The result: The concourse area was transformed from a dark and uninviting bright, safe and colourful environment.

For expert advice, or if you wish to view our previous case studies, please have a look at our website www.cemplas.co.uk



Cemplas Waterproofing & Concrete Repairs Ltd
Cemplas House, 25a, Breakfield, Ullswater Industrial Estate, Coulsdon CR5 2HS

T: 020 8654 3149 F: 020 8656 6984
E: info@cemplas.co.uk W: www.cemplas.co.uk

